DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 12/28/2011 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	(X2) M A. BUI		E CONSTRUCTION 02	(X3) DATE SURVEY COMPLETED	
		155203	B. WING			R 12/22/2011	
NAME OF PROVIDER OR SUPPLIER HILLCREST CENTRE FOR HEALTH AND REHABILITATION				203	ET ADDRESS, CITY, STATE, ZIP CODE 3 SPARKS AVE FFERSONVILLE, IN 47130	12/2	2/2011
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG		PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETION DATE
{K 000}	INITIAL COMMENTS A Post Survey Revis Code Recertification aconducted on 10/31/3 Indiana State Departs accordance with 42 Co Survey Date: 12/22/3 Facility Number: 000 Provider Number: 15 AIM Number: 10027 Surveyor: Mark Bugr Specialist At this PSR survey, Hand Rehabilitation was Requirements for Par Medicare/Medicaid, 4 Life Safety from Fire and National Fire Protecti Life Safety Code (LS) Health Care Occupar Hillcrest Centre for Hitwo story building with constructed at two diff building was built in 1 mixed construction co half inch thick concre	it (PSR) to the Life Safety and State Licensure Survey II was conducted by the ment of Health in SFR 483.70(a). III III0 III0 III0 III20 III, Life Safety Code IIIIIcrest Centre for Health is found in compliance with ticipation in 2 CFR Subpart 483.70(a), and the 2000 edition of the on Association (NFPA) 101, C), Chapter 19, Existing incies and 410 IAC 16.2. IIII IIII IIII IIII IIII IIII IIII		000}		OPRIATE	DATE
ARORATORY	fire barrier walls cons construction on each with metal studs and a mix of concrete and with one half hour rat trusses and wooden	ted smoke barrier walls, two tructed of two hour level, brick exterior walls one half hour rated drywall, I metal stud interior walls ed drywall, and metal rafters in the roof assembly.			TITLE		(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 12/28/2011 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:	1` ′	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02		(X3) DATE SURVEY COMPLETED R 12/22/2011	
		155203	B. WING				
NAME OF PROVIDER OR SUPPLIER HILLCREST CENTRE FOR HEALTH AND REHABILITATION					REET ADDRESS, CITY, STATE, ZIP CODE 203 SPARKS AVE JEFFERSONVILLE, IN 47130	12/2/	2/2011
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		1	ID PROVIDER'S PLAN OF CO PREFIX (EACH CORRECTIVE ACTION TAG CROSS-REFERENCED TO THE DEFICIENCY)		_D BE	(X5) COMPLETION DATE
{K 000}	construction type was construction. The ori an open column foun south length of the far addition including the level 2 East Wing was southeast of the origin foundation was convergential basement for prof Type V (111) construction, the facility is fully sprifice alarm system with corridors and spaces facility has a capacity 80 at the time of this second to the construction of the second type of construction, the facility is fully sprifice alarm system with corridors and spaces facility has a capacity 80 at the time of this second to the construction of the cons	construction type, the facility is classified as Type V (111) ginal building was built with dation exposed at the entire cility. In 1974, a two story level 1 Transcare Unit and is constructed to the mal building and the column erted into a poured finished physical therapy and is also ruction. Because the the addition are the same the facility was surveyed as an smoke detection in the open to the corridors. The	{K (000)			